

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number ST01550LA

This Certificate issued to

Global AirWorks
19933 Harrison Ave.
City of Industry, California 91789

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet.*

Original Product Type Certificate Number: A35EU

Make: Airbus

Model: A300 Model B4-601, -603, -620

Description of Type Design Change: Installation of AirWorks Cockpit Door Surveillance Systems in accordance with FAA Approved AirWorks Index List Document No. IL23007, Revision N/C, dated July 11, 2003, or later FAA approved revision. AirWorks Airplane Flight Manual Supplement Document No. AFMS232010011, Revision Original, FAA approved on October 29, 2003, or later FAA approved revision, is required as part of this modification.

Limitations and Conditions This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application July 19, 2003

Date reissued: July 29, 2004; Oct. 12, 2006,
September 22, 2009

Date of issuance: October 30, 2003

Date amended:



By direction of the Administrator

[Signature]
(Signature)
Supervisor, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office

alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.